



Sterracore Installation Guide.idw


Page 2 of 14

**Step 1.1** Install Base Trim Above Window.

**Step 1.2** Install Backer Rod and Sealant, J Molding Extrusion with Sealant, and Underlayment.








**Step 4.1** Layout Foam Tape and Appropriate Sealant Throughout the Walls.


**Step 4.2** Layout Foam Tape for Corner Trims.



**Step 5.1** Install Window Sill Trim, J Molding Extrusion w/ Sealant, and Backer Rod and Sealant.


**Step 5.2** Slide In Sterracore Panel.

**Step 5.3** Install Transition Extrusion Trims Over Top of Sterracore Panel.



**Step 6.1** Slide in Sterracore Panels into Transition Trim.

**Step 6.2** Install Transition Trim Over Sterracore Panels.





Sterracore Installation Guide.idw

**Step 7.1** Slide Top Panel into Transition Trim.

**Step 7.2** Install Transition Trim on the Side of the Sterracore Panels.


**Step 7.3** Slide in Sterracore Panel into Previously Installed Transition Trim.






**Step 9.1** Fasten Inside Corner Extrusion.

**Step 9.2** Slide SterraCore Panel into Inside Corner Extrusion.




**Step 10.1** Fasten 2nd Outside Corner Extrusion.

**Step 10.2** Slide SterraCore Panel into Outside Corner Extrusion.




**Step 11.1** Fasten Angle Trim with Backer Rod and Sealant.

**Step 11.2** Install Terminal J Molding Extrusion with Sealant Over Angle Trim.



**Step 12.1** Fasten Terminal J Molding Extrusion with Sealant.

**Step 12.2** Install Terminal J Molding Extrusions Along Top of Wall.



**Step 13.1** Install Top Coping System. (Refer to Other Details for Coping System Installation.)

