



DEW POINT OF MOIST AIR CHART

Temperature at which moisture will condense on a surface. No coatings should be applied unless surface temperature is a minimum of 5°F above this point. Temperature must be maintained during curing.

This chart illustrates how to calculate the dew point:

Ambient Air Temperature

Relative Humidity	20°F	-7°C	30°F	-1°C	40°F	4°C	50°F	10°C	60°F	16°C	70°F	21°C	80°F	27°C	90°F	32°C	100°F	38°C	110°F	43°C	120°F	49°C
90	18°F	-8°C	28°F	-2°C	37°F	3°C	47°F	8°C	57°F	14°C	67°F	19°C	77°F	25°C	87°F	31°C	97°F	36°C	107°F	42°C	117°F	47°C
85	17°F	-8°C	26°F	-3°C	36°F	2°C	45°F	7°C	55°F	13°C	65°F	18°C	75°F	24°C	84°F	29°C	95°F	35°C	104°F	40°C	113°F	45°C
80	16°F	-9°C	25°F	-4°C	34°F	1°C	44°F	7°C	54°F	12°C	63°F	17°C	73°F	23°C	82°F	28°C	93°F	34°C	102°F	39°C	110°F	43°C
75	15°F	-9°C	24°F	-4°C	33°F	1°C	42°F	6°C	52°F	11°C	62°F	17°C	71°F	22°C	80°F	27°C	91°F	33°C	100°F	38°C	106°F	42°C
70	13°F	-11°C	22°F	-8°C	31°F	-1°C	40°F	4°C	50°F	10°C	60°F	16°C	68°F	20°C	78°F	26°C	88°F	31°C	96°F	36°C	105°F	41°C
65	12°F	-11°C	20°F	-7°C	29°F	-2°C	36°F	3°C	47°F	8°C	57°F	14°C	66°F	19°C	76°F	24°C	85°F	29°C	93°F	34°C	103°F	39°C
60	11°F	-12°C	19°F	-7°C	27°F	-3°C	36°F	2°C	45°F	7°C	55°F	13°C	64°F	18°C	73°F	23°C	83°F	26°C	92°F	33°C	101°F	38°C
55	9°F	-13°C	17°F	-8°C	25°F	-4°C	34°F	1°C	43°F	6°C	53°F	12°C	61°F	16°C	70°F	21°C	80°F	27°C	89°F	32°C	96°F	37°C
50	6°F	-14°C	15°F	-9°C	23°F	-5°C	31°F	-1°C	40°F	4°C	50°F	10°C	59°F	15°C	67°F	19°C	77°F	25°C	86°F	30°C	94°F	34°C
45	4°F	-16°C	13°F	-11°C	21°F	-6°C	29°F	-2°C	37°F	3°C	47°F	8°C	58°F	13°C	64°F	18°C	73°F	23°C	82°F	28°C	91°F	33°C
40	1°F	-17°C	11°F	-12°C	18°F	-8°C	26°F	-3°C	35°F	2°C	43°F	6°C	52°F	11°C	61°F	16°C	69°F	21°C	78°F	28°C	87°F	31°C
35	-2°F	-19°C	8°F	-13°C	16°F	-9°C	23°F	-5°C	31°F	-1°C	40°F	4°C	48°F	9°C	57°F	14°C	65°F	18°C	74°F	23°C	83°F	28°C
30	-6°F	-20°C	4°F	-16°C	13°F	-11°C	20°F	-7°C	28°F	-2°C	36°F	2°C	44°F	7°C	52°F	11°C	61°F	16°C	69°F	21°C	77°F	25°C

Examples

- Fahrenheit: If ambient air temperature is 70°F and relative humidity is 65%, the dew point is 57°F. No coating should be applied unless the surface temperature is 62°F minimum ($57°F + 5°F = 62°F$).
- Celsius: If temperature is 21°C and the relative humidity is 65%, the dew point is 14°C. No coating should be applied unless the surface temperature is 3°C higher than the dew point, 17°C ($14°C + 3°C = 17°C$).

The information data and suggestions contained herein are believed to be reliable based upon our knowledge and experience; however, it is expressly declared that Seller does not guarantee the result to be obtained in Buyers processes. **SELLER HEREBY EXPRESSLY DISCLAIMS ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND/OR ANY OTHER WARRANTY EXPRESSED OR IMPLIED** as to any and all products and or suggestions described herein whether such products are used along or in combination with other materials. Buyer must make its own determination of the suitability of any product for its use and the completeness of any information contained herein. Nothing contained herein shall be construed to constitute inducement or recommendation to practice any invention covered by any patent without authority from the owner of the patent.