


NOTE:  
 CLEAN AND PRIME MEMBRANE IN LAP AREAS WITH JM TAPE PRIMER/WASH. THE JM TAPE PRIMER/WASH MUST BE COMPLETELY DRY AND TACK FREE BEFORE LAP CEMENT APPLICATION.

DRAWING NO. <b>EB-31</b>	<b>BASE FLASHING WITH PREFABRICATED METAL CURB FLASHING</b>			
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP31BFM	