



**NOTE:**

ALL AREAS THAT ARE ADHERED WITH JM EPDM SEAM TAPE MUST BE CLEANED AND PRIMED WITH JM TAPE PRIMER/WASH.

DRAWING NO.

**EC-7**

**COUNTERFLASHING - EQUIPMENT SUPPORT**

SCALE

N.T.S.

ISSUE DATE

3-06

CAD

SP07CAP

