


NOTE:
 BOTH SURFACES TO BE MATED MUST BE CLEANED WITH JM TAPE PRIMER/WASH.

DRAWING NO. EL-17T	FLASHING TO MEMBRANE TAPE SPLICE FOR MEMBRANE FLASHING			 Johns Manville
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP17LAPA	