

BUILDING PRODUCTS CORP

525 Orange Street P.O. Box 340 Coshocton, Ohio 43812

800-882-7663 740-622-2645 fax: 740-622-6161 www.mfmbp.com



To Whom It May Concern:

This letter is intended to outline the possible contribution of MFM Building Products Corporation *Roofing Underlayments and Water Resistive Barriers'* (WRB) materials to the LEED Green Building Rating System™. The information is in accordance with LEED-2009 for New Construction and Major Renovations of existing buildings.

MR Credit 2.1: Construction Waste Management, Divert 50% from Disposal MR Credit 2.2: Construction Waste Management, Divert 75% from Disposal

In areas where facilities exist, the following MFM Building Products Corporation *Roofing Underlayments* and *Water Resistive Barriers*' packaging materials are recyclable and can contribute to earning Materials and Resources Credit 2.1 or Credit 2.2.

<u>Item</u>	Description	Maximum Weight
Wooden Pallet	wood	45 lbs
Underlayment Core	cardboard	2.0 lbs / core
Underlayment Carton	cardboard	3.5 lbs / carton
WRB Core	cardboard	0.055 lbs / inch*
WRB Carton	cardboard	2.0 lbs / carton
Underlayment Release Liner	PE film	0.004 lbs / per square foot
Underlayment Release Liner	paper	0.018 lbs / per square foot
WRB Release Liner	paper	0.016 lbs / per square foot

^{*} Water Resistive Barriers are available in various lengths and widths.

MR Credit 5.1: Regional Materials MR Credit 5.2: Regional Materials

MFM Building Products Corporation *Roofing Underlayments and Water Resistive Barriers'* materials are manufactured in Coshocton, Ohio (43812) in North America. If this location falls within a 500-mile radius of the project site, then these materials, or a portion of the materials, can contribute to earning Materials and Resources Credit 5.1 and Credit 5.2.

EQ Credit 4.2: Low Emitting Materials, Paints & Coatings

EQ Credit 4.2 pertains to products that are to be used in the interior of a building. MFM Building Products Corporation *Roofing Underlayments and Water Resistive Barriers'* materials are applied onto the exterior of a structure and therefore would not contribute to this credit.

If additional information or clarification is required, please contact me or your local MFM Sales Representative.

Sincerely,

Whit Croft

Whit Croft
MFM Technical Service Manager
wcroft@mfmbp.com • 800-882-7663