

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

SECTION 1: PRODUCT & COMPANY IDENTIFICATION

PRODUCT NAME:	ROOF X TENDER [®] 983		
PRODUCT NUMBER: CATEGORY:	RX-981 Blue Liguid		Beacon Sales Acquisition, Inc.
PRODUCT USE:	Blue Primer	ADDRESS:	505 Huntmar Park Drive, Suite 300 Herndon, VA 20170
MANUFACTURER: ADDRESS:	APOC 4161 E. 7th Avenue		571-323-3939
	Tampa, FL 33605 813-248-2101	INTERNET:	www.becn.com
PHONE: EMERGENCY PHONE:			
EMERGENCET FROME.	CHEMTREC: 1-800-424-9300 Outside USA and Canada: +703-527-3887		
EFFECTIVE DATE:	4/19/2018		

Section 2 - Hazards Identification

	Emergency Overview
	WARNING
	Causes mild skin irritation. Harmful if swallowed.
Prevention	Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash thoroughly after handling.
Response	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If skin irritation occurs: Get medical advice/attention.
Storage/Disposa	al Store in a closed container. Do not allow product to freeze. Dispose of content and/or container in accordance with local, regional, national, and/or international regulations.

TRIBUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

CAUTION - May cause eye and skin irritation on contact.

Physical Form	* L	iquid				
Color	* V	* White Liquid.				
Odor	* A	crylic Paint-Like Odor.				
Flash Point	* >	247 F(> 119.4444 C)				
OSHA (HCS 2012)		kin Corrosion/Irritation - Category 3, Serio A	us Eye Damage, Eye Irritation - Category			
WHMIS	* (Class D - Poisonous and Infectious Material	ls - Division 2 - Subdivision B			
NFPA: Fire instability 0 0 0 0 0 0 0 0 0 0 0 0 0	ects					
Inhalation						
Acute (Immediate)		ion of vapors or mists may cause central n dness, headache, nausea and loss of coor				
Chronic (Delayed)	* Under	normal conditions of use, no health effects	are expected.			
Skin						
Acute (Immediate)	* May ca	ause irritation.				
Chronic (Delayed)	•	ted and prolonged exposure to the skin ma	av cause dermatitis			
	Roped					
Eye Acute (Immediate)		to cause eye irritation, burning, tearing, et ritation persist, seek medical attention.	c. on contact with the eyes. If swelling			
Chronic (Delayed)		contact may cause slight to moderate irrit	ation.			
		, ,				
Ingestion	* May cause	e irritation. May affect the nervous system.	May be barmful or fatal if swallowed			
Chronic (Delayed)	-		-			
Smonie (Delayeu)	 * Repeated and prolonged exposure may cause gastrointestinal disturbances including diarrhea, nausea, and vomiting. 					
		Carcinogenic Effects				

Section 3 - Composition/Information on Ingredients

	Hazardous Components						
Chemical Name	Identifiers	%(weight)	LD50/LC50	Classifications According to Regulation/Directive	Comments		
Polymer Solution	CAS: 25085-34-1	<40.0%					
Calcium Carbonate	CAS: 1317-65-3	<20.0%					
Propylene Glycol	CAS: 57-55-6	1.0%	Ingestion/Oral-Rat LD50 · 20 g/kg				
Texanol Ester	CAS: 25265-77-4	1.0%	Ingestion/Oral-Rat LD50 · 3200 mg/kg				

TRABUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

Non-Hazardous Components					
Chemical Name Identifiers %(weight) LD50/LC50 Classifications According to Regulation/Directive Comme					

This product is an encapsulated mixture which reduces the likelihood of exposure to hazardous particulates. Airborne exposures to hazardous dusts or mists may be generated by spraying, sanding or grinding.

Section 4 - F	Section 4 - First Aid Measures				
Inhalation	* IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. If signs/symptoms continue, get medical attention.				
Skin	* Rinse skin immediately with plenty of water for 15-20 minutes. Take off contaminated clothing. If skin irritation occurs: Get medical advice/attention.				
Еуе	* If eye irritation persists: Get medical advice/attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.				
Ingestion	* If swallowed, do not induce vomiting: seek medical advice immediately and show this container or label.				

Section 5 - Fire Fighting Measures

Extinguishing Media	* LARGE FIRE: Water spray, fog or regular foam. SMALL FIRES: Dry chemical, CO2, water spray or regular foam.
Unsuitable Extinguishing Media	* No data available.
Firefighting Procedures	 * Fire fighters should wear complete protective clothing including self-contained breathing apparatus. Keep unauthorized personnel away.
Unusual Fire and Explosion Hazards	* Product containers may rupture when exposed to extreme heat. Precaustions should be taken to prevent release of materials.
Hazardous Combustion Products	* Non-combustible, substance itself does not burn but may decompose upon heating to produce toxic fumes.
Protection of Firefighters	* Structural firefighters' protective clothing provides limited protection in fire situations ONLY; it is not effective in spill situations where direct contact with the substance is possible.
Flash Point	* > 247 F(> 119.4444 C) CC (Closed Cup)

Section 6 - Accidental Release Measures

Personal Precautions	* Do not touch damaged containers or spilled material unless wearing appropriate protective clothing.
Emergency Procedures	* Isolate the area and contain the spilled material. Persons not wearing the appropriate PPE should be removed from the area until the spill is cleaned up.
Environmental Precautions	* Avoid run off to waterways and sewers.
Containment/Clean-up Measures	 * Absorb or cover with dry earth, sand or other non-combustible material and transfer to containers. Use appropriate Personal Protective Equipment (PPE)
Prohibited Materials	* Avoid contact with strong oxidizing agents and acids.

Section 7 - Handling and Storage

Handling

* KEEP OUT OF THE REACH OF CHILDREN! Keep containers tightly closed when not in use.

TRABUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

Storage

* Avoid extreme temperatures and freezing. Keep container/package tightly closed and in a well-ventilated place.

Special Packaging Materials Incompatible Materials or Ignition Sources

- * Not Applicable.
- * Avoid contact with strong oxidizing agents and acids.

Section 8 - Exposure Controls/Personal Protection

Personal Protective Equipment



Respiratory	* When used with adequate ventilation, a respirator is not normally required. If required, use a NIOSH-approved air purifying respirator with organic vapor cartridge or supplied air respirator. This product is an encapsulated mixture which reduces the likelihood of exposure to hazardous particulates. Airborne exposures to hazardous dusts or mists may be generated by spraying, sanding or grinding.
Eye/Face	* Wear ANSI approved safety glasses with side shields or safety goggles.

- Hands * Wear chemical resistant gloves with repeated or prolonged exposure.
- Engineering Measures/Controls * Adequate ventilation systems as needed to control concentrations of airborne contaminants below applicable threshold limit values. Use precaution to protect building intake from fumes and vapors created outdoors.

Exposure Limits/Guidelines						
	Result	Canada Ontario	Mexico	NIOSH	OSHA	
Propylene Glycol (57-55-6)	TWAs	50 ppm TWAEV (total aerosol and vapour); 155 mg/m3 TWAEV (total aerosol and vapour); 10 mg/m3 TWAEV (for assessing the visibility in a work environment, aerosol only)	Not established	Not established	Not established	
Texanol Ester (25265-77-4	TWAs	50 ppm TWAEV (total aerosol and vapour); 155 mg/m3 TWAEV (total aerosol and vapour);			50 mg/m3 TWA	
Calcium Carbonate (1317-65-3)	TWAs	Not established	10 mg/m3 TWA	10 mg/m3 TWA (total dust); 5 mg/m3 TWA (respirable dust)	15 mg/m3 TWA (total dust); 5 mg/m3 TWA (respirable fraction)	

Section 9 - Physical and Chemical Properties

Material Description			
Physical Form	Liquid	Appearance/Description	Grey liquid with heavy consistency.
Color	Grey Liquid.	Odor	Acrylic Paint-Like Odor.
Taste	No data available.	Particulate Type	Not relevant
Particulate Size	Not relevant	Aerosol Type	Not relevant
Odor Threshold	No data available		
General Properties			
Boiling Point	212 to 245 F(100 to 118.3333 C)	Melting Point	No data available
Decomposition Temperature	No data available	Heat of Decomposition	Not relevant
pН	8 @ 25 C(77 F)	Specific Gravity/Relative Density	1.26 Water=1
Density	10.94 lbs/gal @ 25 C(77 F)	Bulk Density	No data available
Water Solubility	Soluble 100 % @ 25 C(77 F)	Solvent Solubility	Not relevant

TRIBUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

Viscosity	110-115 KU. @ 25 C(77 F)			
Volatility	•			
Vapor Pressure	0.1 mmHg (torr) @ 20 C(68 F)	Vapor Density	> 1 Air=1	
Evaporation Rate	< 1 Ether = 1	VOC (Wt.)	No data available	
VOC (Vol.)	63 g/L	Volatiles (Wt.)	No data available	
Volatiles (Vol.)	No data available			
Flammability				
Flash Point	> 247 F(> 119.4444 C) Flash Point Test Type		CC (Closed Cup)	
UEL	No data available	LEL	No data available	
Autoignition	No data available	Self-Accelerating Decomposition Temperature (SADT)	Not relevant	
Heat of Combustion (ΔHc)	Not relevant	Burning Time	Not relevant	
Flame Duration	Not relevant	Flame Height	Not relevant	
Flame Extension	Not relevant	Ignition Distance	Not relevant	
Environmental				
Half-Life	e Not relevant Octanol/Water Partition coefficient Not		Not relevant	
Coefficient of Water	Not relevant	Bioaccumulation Factor	Not relevant	
Bioconcentration Factor	Not relevant	Biochemical Oxygen Demand BOD/BOD5	Not relevant	
Chemical Oxygen Demand	Not relevant	Persistence	Not relevant	
Degradation	Not relevant			

Section 10 - Stability and Reactivity		
Stability	* Stable under normal temperatures and pressures.	
Hazardous Polymerization	* Hazardous polymerization not indicated.	
Conditions to Avoid	* Excessive heat and freezing.	
Incompatible Materials	* Strong oxidizers and acids.	
Hazardous Decomposition Products	* No known issues under normal usage conditions.	

Section 11 - Toxicological Information

Component Name	CAS	Data
Propylene Glycol	57-55-6	Acute Toxicity: orl-rat LD50:20 gm/kg; skn-hmn TCLo:10 pph; skn-hmn TDLo:5 mg/kg/7D-l; Irritation: skn-hmn 500 mg/7D MLD
Texanol Ester	25265-77-4	Acute Toxicity: orl-rat LD50:3200 mg/kg; ihl-rat LC :>3500 mg/m3/6H
Other Component Information		s concluded that none of the following chemicals in this product are enic to humans.

Section 12 - Ecological Information

Ecological Fate	* No data available.
Persistence/Degradability	* No data available.
Bioaccumulation Potential	* No data available.
Mobility in Soil	* No data available.
Other Information	* Do not allow product exposure to the ground or into any waterway. Do not allow entry into muncipal sewer systems.

Section 13 - Disposal Considerations

TRABUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

Product * Dispose of content and/or container in accordance with local, regional, national, and/or international regulations.

Section 14 - Transportation Information

DOT - United States - Department of Transportation - Shipping Name: Not Regulated.

TDG - Canada - Transportation of Dangerous Goods - Shipping Name: Not Restricted.

IMO/IMDG - International Maritime Transport Shipping Name: Not Regulated.

IATA - International Air Transportation Association - Not Regulated.

Section 15 - Regulatory Information

SARA Hazard Classifications * Acute, Chronic

State Right To Know					
Component	CAS	MA	MN	NJ	PA
Polymer Solution	25085-34-1	No	No	No	No
Calcium Carbonate	1317-65-3	Yes	Yes	Yes	Yes
Propylene Glycol	57-55-6	No	Yes	Yes	Yes
Texanol Ester	25265-77-4	No	No	No	No

Inventory			
Component	CAS	EU EINECS	TSCA
Polymer Solution	25085-34-1	No	No
Calcium Carbonate	1317-65-3	Yes	Yes
Propylene Glycol	57-55-6	Yes	Yes
Texanol Ester	25265-77-4	Yes	Yes

Canada

Labor Canada - WHMIS - Classifications of Substances

oundud minino	olacomoullo	
●Calcium Carbonate	1317-65-3	D2A
Propylene Glycol •Texanol Ester	57-55-6 25265-77-4	Uncontrolled product according to WHMIS classification criteria Uncontrolled product according to WHMIS classification criteria

United States

 U.S. - CERCLA/SARA - Hazardous
 Substances and their Reportable Quantities

 • Calcium Carbonate
 1317-65-3
 Not Listed

 • Propylene Glycol
 57-55-6
 Not Listed

•Texanol Ester 25265-77-4 Not Listed

United States - California

Environment

U.S. - California - Proposition 65 - Carcinogens List • Calcium Carbonate 1317-65-3 Not Listed • Propylene Glycol 57-55-6 Not Listed • Texanol Ester 25265-77-4 Not Listed

United States - Rhode Island

Labor

U.S. - Rhode Island - Hazardous Substance List

•Calcium Carbonate 1317-65-3 Toxic

Propylene Glycol 57-55-6 Combustible

TRIBUILT

ROOF X TENDER® 983 Ultra Base Elastomeric Roof Primer

- •Texanol Ester 25265-77-4 Not Listed
- **Other Information** * WARNING: This product contains a chemical known to the State of California to cause cancer.

Section 16 - Other Information

Preparation Date	* 3/3/2017
Last Revision Date	* 5/4/2016
Disclaimer/Statement of Liability	This information relates to the specific material designated and may not be valid for such material used in combination with any other materials or in any process. Such information is to the best of our knowledge and belief, accurate and reliable as of the date compiled. However, no representation, warranty or guarantee is made as to its accuracy, reliability or completeness. It is the user's responsibility to verify the suitability and completeness of such information for particular use. Gardner Gibson or Beacon Sales Acquisition does not accept liability for any loss or damage that may occur from the use of this information.