



## Product Selection Guide

### Repair Mortars

| Product Name         | Depth of Placement |              |                 | Extension<br>(Pea Gravel) | Corrosion<br>Inhibitor | Shrinkage<br>Compensated | Latex/Polymer<br>Modified | Epoxy<br>Based | Vertical /<br>Overhead | Horizontal | Form/Pour | Notes    |
|----------------------|--------------------|--------------|-----------------|---------------------------|------------------------|--------------------------|---------------------------|----------------|------------------------|------------|-----------|----------|
|                      | Min.               | Max.<br>Neat | Max<br>Extended |                           |                        |                          |                           |                |                        |            |           |          |
| Polyfast FS          | 1/4"               | 2" per lift  | 4"              | 15lbs                     |                        |                          |                           |                |                        |            |           |          |
| Recrete 5 Minute     | 1/8"               | 2" per lift  | 4"              | 25lbs                     |                        |                          |                           |                |                        |            |           |          |
| Recrete 20 Minute    | 1/8"               | 2" per lift  | 4"              | 25lbs                     |                        |                          |                           |                |                        |            |           |          |
| Recrete Light 20 Min | 1/8"               | 2" per lift  | 4"              | 25lbs                     |                        |                          |                           |                |                        |            |           |          |
| Architectural Finish | Feather            | 1/8"         | NA              | NA                        |                        |                          |                           |                |                        |            |           |          |
| Superior Wall Finish | Feather            | 2"           | NA              | NA                        |                        |                          |                           |                |                        |            |           | #9       |
| Perma Patch VO       | 1/4"               | 2" per lift  | NA              | NA                        |                        |                          |                           |                |                        |            |           |          |
| HD 25 VO             | 1/4"               | 2" per lift  | 4"              | 15lbs                     |                        |                          |                           |                |                        |            |           | #4,8     |
| Civil/Structural VO  | 3/8"               | 2" per lift  | NA              | NA                        |                        |                          |                           |                |                        |            |           | #1,4     |
| Civil/Structural FPX | 1"                 | 12"          | NA              | NA                        |                        |                          |                           |                |                        |            |           | #2       |
| Perma Patch FP       | 1/4"               | 2"           | 4"              | 15-30lbs                  |                        |                          |                           |                |                        |            |           | #2       |
| Thin Resurfacer      | Feather            | 1/2"         | NA              | NA                        |                        |                          |                           |                |                        |            |           | #3       |
| Special Patch        | 1/8"               | 2" per lift  | 4"              | 30#                       |                        |                          |                           |                |                        |            |           |          |
| HD 50                | 1/2"               | 2" per lift  | 6"              | 30lbs                     |                        |                          |                           |                |                        |            |           | #2,4,5,8 |
| Pave Patch 3000      | 1/2"               | 2" per lift  | 6"              | 30lbs                     |                        |                          |                           |                |                        |            |           | #2,5     |
| DOT Rapid Repair     | 1/2"               | 2" per lift  | 8"              | 30lbs                     |                        |                          |                           |                |                        |            |           |          |
| Rapid Resin Repair   | 1/2"               | 3"           | NA              | NA                        |                        |                          |                           |                |                        |            |           | #6       |
| Sure Patch           | 1/2"               | 3"           | 6"              | 50%                       |                        |                          |                           |                |                        |            |           | #7       |
| ProPatch VO          | 1/4"               | 2"           | NA              | NA                        |                        |                          |                           |                |                        |            |           |          |

Blue cells indicate that the description or specification applies to the product.

#### Notes:

1. Silica fume enhanced. Can be applied by low velocity spray
2. Excellent for Form & Pump and Form & Pour
3. Minimum depth of 1/8" for improved performance
4. Fiber enhanced
5. Excellent for Dowel Bar Retrofit Mortar
6. Cures in temperatures as low as -20°F (-29°C)
7. Low modulus repair mortar for interior/exterior repairs
8. Calcium Aluminate-based
9. Vertically 2" thick, Overhead up to 1/8" thick

5/13/2024