SAFETY DATA SHEET

1. Identification

Product identifier Glass Mat Faced Gypsum Panels

Product list Product List A

DensArmor Plus® Interior Panel

DensArmor Plus® Fireguard® Abuse-Resistant Panels DensArmor Plus® Fireguard® Impact-Resistant Panels

DensArmor Plus® Fireguard® Interior Panels

DensDeck® Prime Roof Board

DensDeck® Roof Board

DensDeck® Prime Fireguard® Roof Board DensDeck® Fireguard® Roof Board DensDeck® StormX™ Prime Roof Board

DensElement® Sheathing

DensGlass® Fireguard® Sheathing

DensGlass® Shaftliner DensGlass® Sheathing

DensShield® Fireguard® Tile Backer

DensShield® Tile Backer

.....

Product List B

DensArmor Plus® Fireguard C® Interior Panels

.....

Other means of identification

Product code GP-71C

Recommended use Products accommodate a wide range of wall, floor, ceiling and roof applications.

Recommended restrictions None known.

Manufacturer/Importer/Supplier/Distributor information

Company nameGeorgia-Pacific Gypsum LLCAddress133 Peachtree Street, NE

Atlanta, GA 30303

Telephone Technical Information 800.225.6119

(M)SDS Request 404.652.5119

E-mail Not available.

Emergency phone number Chemtrec - Emergency 800.424.9300

2. Hazard(s) identification

Emergency overview Cutting, sanding, or otherwise working with this product may generate large amounts of dust. Dust

may be irritating to eyes, skin and respiratory system.

Physical hazards Not classified.
Health hazards Not classified.
Environmental hazards Not classified.
OSHA defined hazards Not classified.

Label elements

Hazard symbol None.
Signal word None.

Hazard statement The mixture does not meet the criteria for classification.

Precautionary statement

Prevention Observe good industrial hygiene practices.

Response Wash hands after handling. Get medical advice/attention if you feel unwell.

Storage Store away from incompatible materials (see Section 10 of the SDS).

Disposal Dispose of contents/container in accordance with applicable regulations.

Hazard(s) not otherwise classified (HNOC)

None known.

Supplemental information

None.

3. Composition/information on ingredients

Mixtures

Chemical name	Common name and synonyms	CAS number	%
CALCIUM SULFATE DIHYDRATE		10101-41-4	80 - 100
VERMICULITE**		1318-00-9	0 - 10
CONTINUOUS FILAMENT GLASS FIBER		65997-17-3	1 - 5
CRYSTALLINE SILICA (QUARTZ)*		14808-60-7	0.1 - 1

Composition comments

** Found in products in List B, Section 1 of this SDS.

Gypsum (calcium sulfate, dihydrate) and vermiculite contain naturally occurring crystalline silica (quartz) which is listed as a lung carcinogen. See Section 8 for exposure information.

*The weight percent for crystalline silica represents total crystalline silica and not the respirable fraction. Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during activities associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded.

4. First-aid measures

Inhalation If dust from the material is inhaled, remove the affected person immediately to fresh air. Call a

physician if symptoms develop or persist.

Skin contact For skin contact, wash immediately with soap and water. Get medical attention if irritation develops

and persists.

Do not rub the eyes. Immediately flush eyes with plenty of water for at least 15 minutes. Remove Eye contact

contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical

Provide general supportive measures and treat symptomatically. Keep victim under observation.

Irritation of eyes. Exposed individuals may experience eye tearing, redness, and discomfort.

advice/attention.

Rinse mouth. May result in obstruction and irritation if ingested. Get medical attention. Ingestion

Most important

symptoms/effects, acute and

delayed

Indication of immediate medical attention and special

treatment needed

Symptoms may be delayed.

Ensure that medical personnel are aware of the material(s) involved, and take precautions to General information

protect themselves.

5. Fire-fighting measures

Suitable extinguishing media Use extinguishing measures that are appropriate to local circumstances and the surrounding

environment.

Unsuitable extinguishing

media

None known.

Specific hazards arising from

the chemical

During fire, gases hazardous to health may be formed.

Special protective equipment

and precautions for firefighters

Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

Fire fighting

equipment/instructions

Firefighters should wear full protective clothing including self contained breathing apparatus.

Specific methods Use standard firefighting procedures and consider the hazards of other involved materials.

General fire hazards No unusual fire or explosion hazards noted.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Wear appropriate protective equipment and clothing during clean-up. For personal protection, see section 8 of the SDS. Avoid inhalation of dust from the spilled material. Use a NIOSH/MSHA approved respirator if there is a risk of exposure to dust/fume at levels exceeding the exposure limits. Use personal protection recommended in Section 8. Keep unnecessary personnel away.

Methods and materials for containment and cleaning up

Avoid the generation of dusts during clean-up. Collect dust using a vacuum cleaner equipped with HEPA filter. This product is miscible in water. Stop the flow of material, if this is without risk.

Large Spills: Wet down with water and dike for later disposal. Shovel the material into waste container. Following product recovery, flush area with water.

Small Spills: Sweep up or vacuum up spillage and collect in suitable container for disposal. Minimize dust generation. Sweep up or gather material and place in an appropriate container for disposal. Utilize wet methods, if appropriate, to minimize dust. For waste disposal, see section 13 of the SDS.

Environmental precautions

Keep out of drains, sewers, ditches, and waterways.

7. Handling and storage

Precautions for safe handling

Practice good housekeeping. Provide appropriate exhaust ventilation at places where dust is formed. Minimize dust generation and accumulation. Do not breathe dust. Do not get this material in contact with eyes. Do not taste or swallow. Avoid prolonged exposure. Use only in well-ventilated areas. Wear appropriate NIOSH/MSHA approved dust mask or filtering facepiece if dust is generated. Do not eat or drink while using the product. Wash hands before eating, drinking, or smoking.

Conditions for safe storage, including any incompatibilities

Store in tightly closed container. Store level and keep dry. Dewpoint or other conditions causing the presence of moisture can damage the product during storage. Store away from incompatible materials (see Section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

The following constituents are the only constituents of the product which have a PEL, TLV or other recommended exposure limit. At this time, the other constituents have no known exposure limits.

US. OSHA Table Z-1 Permissible Exp Components	oosure Limits (PEL) for A Type	ir Contaminants (29 CFR 1910.10 Value	000) Form
CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4)	PEL	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7)	PEL	0.05 mg/m3	Respirable dust.
US. OSHA Table Z-3 Permissible Exp	oosure Limits (PEL) for N	lineral Dusts (29 CFR 1910.1000)	
Components	Туре	Value	Form
CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4)	TWA	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
		50 mppcf	Total dust.
		15 mppcf	Respirable fraction.
VERMICULITE** (CAS 1318-00-9)	TWA	5 mg/m3	Respirable fraction.
		15 mg/m3	Total dust.
ACGIH			
Components	Туре	Value	Form
CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4)	TWA	3 mg/m3	Respirable Particles.
CONTINUOUS FILAMENT GLASS FIBER (CAS 65997-17-3)	TWA	5 mg/m3	Inhalable fraction.
VERMICULITE** (CAS 1318-00-9)	TWA	3 mg/m3	Respirable particles.

(QUARTZ)* (CAS 14808-60-7) VERMICULITE** (CAS 1318-00-9) NIOSH. Immediately Dangerous to Life or Health (IDLH) Values, as amended Components Type Value CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4) CRYSTALLINE SILICA (QUARTZ)* (CAS 101014-41-4) TWA 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silic should be monitored and controlled. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silic aduring actiassociated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded propriate engineering Score and snap method recommended. When using product, provide local and general external carbon and controlled carbon and general external carbon and controlled carbon and general external carbon and controlled carbon and general external carbo	US. ACGIH Threshold Limit Components	Туре	Value	Form	
GLASS FIBER (CAS 65997-17-3) CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) VERMICULITE** (CAS TWA 10 mg/m3 Inhalable particles. TWA Value CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Type Value Form CALCIUM SULFATE DITYPRATE (CAS 10101-41-4) TWA 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 10101-41-4) 10 mg/m3 Respirable. DITYPRATE (CAS 10101-41-4) No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silic abridance associated with the normal use of this product, however, jobsite air monitoring should be monitored and controlled. "Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during active associated with the normal use of this product, however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded propriate engineering successing: If engineering measures are not sufficient to maintain concentrations of olds: ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, and processing; If engineering measures are not sufficient to maintain concentrations of olds: particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection neasures, such as personal protective equipment Safety glasses or googles are recommended when using this product. Ensure compliance of Safety profession of Safety Polessional protective equipment Safety glasses or googles are recommended when using this product. Ensure compliance of Safety professional formation is recommended to prevent drying or irritation of skin. Safety showerieye wash fountain	DIHYDRATE (CAS	TWA	10 mg/m3	Inhalable fraction.	
CRYSTALLINE SILICA (QUARTZ)* (CAS TWA 10 mg/m3 Inhalable particles. 1318-00-9) NIOSH. Immediately Dangerous to Life or Health (IDLH) Values, as amended Components Type Value CRYSTALLINE SILICA (QUARTZ)* (CAS IDLH 50 mg/m3 Inhalable particles. 14808-60-7) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) (QUARTZ)* (CAS 14808-60-7) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) (Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 1010-141-4) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) (Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 1010-141-4) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) (Components Type Value Form 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Nogical limit values No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica during acti associated with the normal use of this product, however, jobsite air monitoring should be monitored and controlled. **Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product, however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or furmes that may be generated during handling or them processing. If engineering measures are not sufficient to maintain concentrations of dust of the particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection measures, such as personal protective equipment Eye/face protection For prolonged or repeated skin contact use suitable protective gloves. Skin protection Hand protection For prolonged or repeated skin contact use suitable protective gloves. Imper	GLASS FIBER (CAS	TWA	1 fibers/cm3	Fiber.	
NIOSH. Immediately Dangerous to Life or Health (IDLH) Values, as amended Components	CRYSTALLINE SILICA (QUARTZ)* (CAS	TWA	0.025 mg/m3	Respirable fraction.	
CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) U.S. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4) CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Iological limit values posure guidelines No biological exposure limits noted for the ingredient(s). Cocupational exposure to nuisance dust (total and respirable crystalline silic about be conducted to determine actual exposure when permissible exposure limits may be exceeded propriate engineering approved to determine actual exposure when permissible exposure limits may be generated during handling or therm processing, if engineering measures are not sufficient to maintain concentrations of dust ventilation should be sufficient to effective in and prevent buildup of any dusts or fumes that may be generated during handling or therm processing, if engineering measures are not sufficient to maintain concentrations of dust ventilation should be sufficient to effective in maintain particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection worn. Skin protection Hand protection Other Respiratory protection Other Respiratory protection A NIOSH approved dust make or filtering facepiece is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in poorly ventilated are when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a	VERMICULITE** (CAS	TWA	10 mg/m3	Inhalable particles.	
(QUARTZ)* (CAS 14808-60-7) US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4) TWA 5 mg/m3 Respirable. 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Respirable dust. Occupational exposure limits noted for the ingredient(s). Posure guidelines Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silic should be monitored and controlled. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during active associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or them processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection mosures, such as personal protective equipment Safety glasses or goggles are recommended when using this product. Ensure compliance on OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection Other Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area (29) 1910.151 (e)). Impervious protective clothing and gloves recommended in poorty ventilated any when permissible exposure limits may be exceeded. Respirators should be selected by an under the directivo of a trained health and safety professional following requirements found					
US. NIOSH: Pocket Guide to Chemical Hazards Recommended Exposure Limits (REL) Components Type Value Form CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4) 10 mg/m3 Respirable. 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Rodigical limit values Prosure guidelines No biological exposure limits noted for the ingredient(s). Posure guidelines Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica during acti associated with the normal use of this product, brower, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded. Propriate engineering trtrols Score and snap method recommended. When using product, provide local and general ext ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or therm processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection morn. Safety glasses or goggles are recommended when using this product. Ensure compliance on CSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection For prolonged or repeated skin contact use suitable protective gloves. Impervious protective clothing and gloves recommended to prevent drying or irritation of skin Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (har protection). Safety shower/eye wash fountain is recommended in the workplace area (29) (1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29) (1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29) (1910.151 (c)). Impervious protective clothing and gloves re	(QUARTZ)* (CAS	IDLH	50 mg/m3		
DIHYDRATE (CAS 10101-41-4) 10 mg/m3 Total CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) No biological exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silic should be monitored and controlled. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits. Use wet methods, if appropriate engineering ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or them processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection nown. Invidual protection measures, such as personal protective equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Other Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recomme	US. NIOSH: Pocket Guide to		-	Form	
CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Plogical limit values (Coupartional exposure limits noted for the ingredient(s). Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silic should be monitored and controlled. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during act associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded the propriate engineering appropriate engineering appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or therm processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection nown. Idividual protection measures, such as personal protective equipment Eye/face protection Safety glasses or googgles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Pro prolonged or repeated skin contact use suitable protective gloves. Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (har protection). Safety shower/eye wash fountain is recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in the workplace area. A NIOSH approved dust mask or filtering facepiece is recommended in the workplace area.	DIHYDRATE (CAS	TWA	5 mg/m3	Respirable.	
A A A A A A A A A A	,		10 mg/m3	Total	
Occupational exposure to nuisance dust (total and respirable) and respirable crystalline sili should be monitored and controlled. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded propriate engineering antrols Score and snap method recommended. When using product, provide local and general extractional exposure in the conduction of use pairborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or therm processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection worn. Ividual protection measures, such as personal protective equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection For prolonged or repeated skin contact use suitable protective gloves. Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (har protection)). Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated ar when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found	(QUARTZ)* (CAS	TWA	0.05 mg/m3	Respirable dust.	
*Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded. *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during acti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded. *Score and snap method recommended. When using product, provide local and general ext ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and provessing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection nown. *Invidual protection measures, such as personal protective equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of Safety equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of Safety equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of Safety equipment Safety glasses or goggles are recommended to prevent drying or irritation of skin protection). Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in the workplace area. A NIOSH approved dust mask or filtering facepiece is recommended i	ological limit values	No biological exposure limits noted fo	r the ingredient(s).		
associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded propriate engineering ntrols Score and snap method recommended. When using product, provide local and general extended when using product, provide local and general extended to propriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or them processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection in worm. Ilividual protection measures, such as personal protective equipment Safety glasses or goggles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection Other Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (har protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated are when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found	posure guidelines	Occupational exposure to nuisance dust (total and respirable) and respirable crystalline silica should be monitored and controlled.			
ventilation to keep airborne dust concentrations below exposure limits. Use wet methods, if appropriate, to reduce the generation of dust. Ventilation should be sufficient to effectively and prevent buildup of any dusts or fumes that may be generated during handling or therm processing. If engineering measures are not sufficient to maintain concentrations of dust particulates below the Occupational Exposure Limit (OEL), suitable respiratory protection movern. Iividual protection measures, such as personal protective equipment Eye/face protection Safety glasses or goggles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection Hand protection For prolonged or repeated skin contact use suitable protective gloves. Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (han protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 of 1910.151 (c)). Impervious protective clothing and gloves recommended in the workplace area. Respiratory protection Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated are when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found		*Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during activiti associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded.			
Safety glasses or goggles are recommended when using this product. Ensure compliance of OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection Other Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (han protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated and when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements founds.	propriate engineering ntrols	ventilation to keep airborne dust conc appropriate, to reduce the generation and prevent buildup of any dusts or fu processing. If engineering measures particulates below the Occupational E	entrations below exposure lim of dust. Ventilation should be imes that may be generated d are not sufficient to maintain o	its. Use wet methods, if sufficient to effectively rem uring handling or thermal oncentrations of dust	
OSHA's PPE standard (29 CFR 1910.132 and .133) for eye and face protection. Eye wash fountain is recommended. Skin protection Hand protection Other Impervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (han protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 to 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated are when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found	ividual protection measures	such as personal protective equipme	ent		
Hand protectionFor prolonged or repeated skin contact use suitable protective gloves.OtherImpervious protective clothing and gloves recommended to prevent drying or irritation of sk Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (han protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 or 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying or irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area.Respiratory protectionA NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated ar when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found	Eye/face protection	OSHA's PPE standard (29 CFR 1910			
Ensure compliance with OSHA's PPE standards (29 CFR 1910.132 (general) and 138 (han protection)). Safety shower/eye wash fountain is recommended in the workplace area (29 of 1910.151 (c)). Impervious protective clothing and gloves recommended to prevent drying of irritation of skin. Safety shower/eye wash fountain is recommended in the workplace area. Respiratory protection A NIOSH approved dust mask or filtering facepiece is recommended in poorly ventilated are when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements founds.	-	For prolonged or repeated skin contact	ct use suitable protective glove	es.	
when permissible exposure limits may be exceeded. Respirators should be selected by an under the direction of a trained health and safety professional following requirements found	Other	Ensure compliance with OSHA's PPE protection)). Safety shower/eye wash 1910.151 (c)). Impervious protective of	standards (29 CFR 1910.132) fountain is recommended in t clothing and gloves recommen	(general) and 138 (hand he workplace area (29 CFI ded to prevent drying or	
(Z88.2).	Respiratory protection	when permissible exposure limits may	be exceeded. Respirators st	nould be selected by and u	

Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective

equipment to remove contaminants. Keep away from food and drink.

General hygiene considerations

9. Physical and chemical properties

Appearance Gypsum boards

Physical state Solid.
Form Solid

Color Facing color varies

Odor Low odor
Odor threshold Not available.
pH > 6 - < 8

Melting point/freezing point Not applicable.

Initial boiling point and boiling Not applicable.

range

Flash point

Evaporation rate

Not applicable.

Flammability (solid, gas)

Upper/lower flammability or explosive limits

Explosive limit - lower (%)

Not applicable.

Explosive limit - upper (%)Not applicable.Vapor pressureNot applicable.Vapor densityNot applicable.Relative densityNot available.

Solubility(ies)

Solubility (water) 0.2 % @ 22°C

Partition coefficient Not applicable.

(n-octanol/water)

Auto-ignition temperatureNot applicable.Decomposition temperatureNot available.ViscosityNot applicable.

Other information

Flash point class Not flammable Specific gravity > 2.2 - < 2.4

10. Stability and reactivity

Reactivity Contact with strong acids produces carbon dioxide.

Chemical stability Material is stable under normal conditions.

Possibility of hazardous

reactions

No dangerous reaction known under conditions of normal use.

Conditions to avoid Contact with incompatible materials. Avoid dispersal of dust in the air (i.e., clearing dust surfaces

with compressed air).

Incompatible materials Strong acids.

Hazardous decomposition

products

May include and are not limited to: calcium oxide and sulfur dioxide.

11. Toxicological information

Information on likely routes of exposure

Inhalation Inhalation of dusts may cause respiratory irritation.

Skin contact Dust or powder may irritate the skin. Frequent or prolonged contact may defat and dry the skin,

leading to discomfort and dermatitis.

Eye contact Dust generated during processing may cause eye irritation.

Ingestion Not applicable under normal conditions of use. May cause gastrointestinal irritation if ingested.

Symptoms related to the physical, chemical and toxicological characteristics

Dusts may irritate the respiratory tract, skin and eyes.

Information on toxicological effects

Acute toxicity

Product Test Results Species

Glass Mat Faced Gypsum Panels

Acute

Oral

LD50 Rat 1728 mg/kg Components **Test Results** Species

CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4)

Acute Oral

LD50 Rat > 1581 mg/kg

Skin corrosion/irritation Serious eye damage/eye

Dust generated during processing may cause eye irritation.

Prolonged skin contact may cause temporary irritation.

irritation

Respiratory or skin sensitization

Respiratory sensitization Not likely to cause respiratory sensitization.

Skin sensitization This product is not expected to cause skin sensitization.

Germ cell mutagenicity Not classified.

Carcinogenicity Not expected to be hazardous by OSHA/WHMIS criteria.

> Exposure to respirable crystalline silica in the form of quartz or cristobalite from occupational sources is listed by IARC and NTP as a lung carcinogen. Prolonged exposure to respirable crystalline silica has been known to cause silicosis, a lung disease, which may be disabling. While there may be a factor of individual susceptibility to a given exposure to a respirable silica dust, the risk of contracting silicosis and the severity of the disease is clearly related to the amount of respirable crystalline silica exposure and the length of time (usually years) of exposure.

IARC Monographs. Overall Evaluation of Carcinogenicity

CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) 1 Carcinogenic to humans.

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1053)

CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Cancer

US. National Toxicology Program (NTP) Report on Carcinogens

CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Known To Be Human Carcinogen.

Reproductive toxicity Not classified. Specific target organ toxicity -Not classified.

single exposure

Specific target organ toxicity -

repeated exposure

Not classified.

Aspiration hazard

Not classified.

Chronic effects Not hazardous under normal conditions of use.

Further information *Testing conducted by Georgia-Pacific did not detect respirable crystalline silica during activities

associated with the normal use of this product; however, jobsite air monitoring should be conducted to determine actual exposure when permissible exposure limits may be exceeded.

12. Ecological information

Not considered to be harmful to aquatic life. **Ecotoxicity**

Species Test Results Components

CALCIUM SULFATE DIHYDRATE (CAS 10101-41-4)

Aquatic Acute

Fish LC50 Fathead minnow (Pimephales promelas) > 1970 mg/l, 96 hours

> 1970 mg/l, 96 hours

CONTINUOUS FILAMENT GLASS FIBER (CAS 65997-17-3)

Aquatic

Acute

Fish LC50 Fish > 1000 mg/l, 96 hours

Material name: Glass Mat Faced Gypsum Panels

SDS US

Components Species Test Results

CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7)

Aquatic

Acute

Fish LC50 Zebra danio (Danio rerio) > 10000 mg/l, 96 Hours OECD SIDS

Persistence and degradability No data is available on the degradability of this product.

Bioaccumulative potential No data available.

Mobility in soil No data available.

Other adverse effects No other adverse environmental effects (e.g. ozone depletion, photochemical ozone creation

potential, endocrine disruption, global warming potential) are expected from this component.

13. Disposal considerations

Disposal instructionsUnder RCRA, it is the responsibility of the user of the product to determine, at the time of disposal,

whether the product meets RCRA criteria for hazardous waste. Dispose of contents/container in

accordance with local/regional/national/international regulations.

Local disposal regulations Dispose in accordance with all applicable regulations.

Hazardous waste code

The waste code should be assigned in discussion between the user, the producer and the waste

disposal company.

Waste from residues / unused

products

Dispose of in accordance with local regulations.

Contaminated packaging Not available.

14. Transport information

DOT

Not regulated as dangerous goods.

IATA

Not regulated as dangerous goods.

IMDG

Not regulated as dangerous goods.

Transport in bulk according to Annex II of MARPOL 73/78 and

Not applicable.

the IBC Code

15. Regulatory information

US federal regulations This product is not known to be a "Hazardous Chemical" as defined by the OSHA Hazard

Communication Standard, 29 CFR 1910.1200.

the TSCA 8(b) inventory.

TSCA Section 12(b) Export Notification (40 CFR 707, Subpt. D)

Not regulated.

CERCLA Hazardous Substance List (40 CFR 302.4)

Not listed

SARA 304 Emergency release notification

Toxic Substances Control Act (TSCA)

Not regulated.

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1053)

CRYSTALLINE SILICA (QUARTZ)* (CAS 14808-60-7) Cancer

lung effects

immune system effects

All components of the mixture are designated as "active" on or exempt from

kidney effects

Superfund Amendments and Reauthorization Act of 1986 (SARA)

SARA 302 Extremely hazardous substance

Not listed.

SARA 311/312 Hazardous No

chemical

SARA 313 (TRI reporting)

Not regulated.

Other federal regulations

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

Not regulated.

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Not regulated.

Safe Drinking Water Act

Not regulated.

(SDWA)

US state regulations

California Proposition 65

This product contains no listed substances known to the State of California to cause cancer, birth defects or other reproductive harm, at levels which would require a warning under the statute.

International Inventories

On inventory (yes/no)* Country(s) or region Inventory name Canada Domestic Substances List (DSL) Yes United States & Puerto Rico Toxic Substances Control Act (TSCA) Inventory Yes

16. Other information, including date of preparation or last revision

Issue date March-13-2015 December-15-2022 **Revision date**

Version # 08

Health: 0 **HMIS®** ratings

Flammability: 1 Physical hazard: 0

Health: 0 NFPA ratings

Flammability: 0 Instability: 0

Disclaimer This SDS is intended to quickly provide useful information to the user(s) of this material or product.

> It is not intended to serve as a comprehensive discussion of all possible risks or hazards, and it assumes a reasonable use of the product. The information contained in this SDS is believed to be accurate as of the date of preparation of this SDS and has been compiled from sources believed to be reliable. It is offered for your consideration, investigation and verification. The user or handler (or their employer) should consider the specific conditions in which this material will be used, handled, or stored and determine what specific safety or other precautions are required. Employers should ensure that their employees, agents, contractors, and customers who will use the product receive adequate warnings and safe handling procedures, including a current SDS. Product users or handlers (or their employer) who are unsure of what specific precautions are required should consult their employer, product supplier, or safety or health professionals before handling or working with this product. Please notify us immediately if you believe this SDS or other

safety and health information about this product is inaccurate or incomplete.

This document has undergone significant changes and should be reviewed in its entirety. **Revision information**

Material name: Glass Mat Faced Gypsum Panels

8/8

GP-71C Version #: 08 Revision date: December-15-2022 Issue date: March-13-2015

^{*}A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s) A "No" indicates that one or more components of the product are not listed or exempt from listing on the inventory administered by the governing