


NOTES:

1. PICTURE FRAME VENTS OR CURBS EXHAUSTING CONTAMINANTS ADDITIONAL MEMBRANE.
2. SACRIFICIAL SHEET MUST COVER THE ENTIRE AREA THAT MAY BE AFFECTED.

ANY DAMAGE TO THE ROOF SYSTEM THAT RESULTS FROM IMPROPER MAINTENANCE OR BY EXCESSIVE DISCHARGE FROM VENTS IS NOT GUARANTEEABLE

DRAWING NO. PM-97	SACRIFICIAL SHEET AT EXHAUST VENT			 Johns Manville
	SCALE N.T.S.	ISSUE DATE 3-06	CAD PV97MEF	