


NOTES:

1. ONLY USABLE FOR FLASHING APPLICATIONS.
2. DO NOT FEATHER JM EPDM LAP CAULK.
3. BOTH SURFACES TO BE MATED MUST BE CLEANED WITH JM EPDM TAPE PRIMER/WASH. THE JM TAPE PRIMER/WASH MUST BE COMPLETELY DRY AND TACK FREE BEFORE LAP CEMENT APPLICATION.

DRAWING NO. EL-1	FLASHING LAP SPLICE			
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP01LAP	