



MATERIAL SAFETY DATA SHEET

HMIS
H = 0
F = 0
R = 0
PPE = See Section 8

Section I

Manufacturer: Siplast, an Icopal Group Company
(800) 643-1591 or (800) 922-8800
Address: 1000 E. Rochelle Blvd., Irving, TX 75062-3940
Emergency Phone No.: CHEMTREC, (800) 424-9300 (U.S.), (703) 527-3887 (outside of U.S.)
Product Class: Liquid-applied Waterproofing System Component
Trade Name: Pro Texture

Section II - Ingredients

Chemical Family: Glass Oxide
CAS Number: 65997-17-13

| Ingredient | NTP/IRAC OSHA CARC. | Percent | ACGIH TLV | OSHA PEL TWA |
|----------------------------|------------------------|---------|------------------------|------------------------|
| Nuisance Dust | - | - | 10 mg / m ³ | 15 mg / m ³ |
| Nuisance Dust - Respirator | - | - | 5 mg / m ³ | 5 mg / m ³ |

Glass beads are not considered to be hazardous by the EPA under 29 CFR 1910.1200 and the Federal Register, Vol. 51, No. 221, pp. 41582-41594. The RCRA status of unused material is not hazardous according to the list of CERCLA chemicals. It is not on the toxic chemical list in the Committee Print Number 99-169.

Section III - Physical Data

Appearance & Odor: White, No taste or odor
Vapor Pressure: N/A
Vapor Density (Air = 1): N/A
Melting Point: >1100°F
Specific Gravity (H₂O=1, at 4°C): 2.4 - 2.6
Solubility in H₂O: N/A
Boiling Point: Not measurable
Evaporation Rate: (Butyl Acetate = 1) N/A

Section IV - Fire and Explosion Data

DOT Category: N/A
Flash Point: N/A
Flammable Limits: Does not ignite
Extinguishing Media: Not a fire hazard
Unusual Fire or Explosion Hazards: None
Special Fire-Fighting Procedures: None
LEL %: N/A UEL %: N/A

Section V - Health Hazard Data

Summary of Risks:
Health Hazards: None
Carcinogenicity: No
Routes of Entry: Inhalation, Ingestion
Work/Hygienic Practices: Wash hands after handling beads and before.
Effects of Overexposure: May cause temporary respiratory and eye irritation.
Emergency and First Aid Procedures: If beads or dust cause eye irritation, flush the affected eye(s) with water or commercial eye wash. If existing respiratory/conditions are aggravated in your use of this product, get to a well ventilated area. Seek medical attention for either emergency if condition is not alleviated.

Section VI - Reactivity Data

Stability: Stable Unstable _____

Conditions to Avoid: None

Hazardous Decomposition Products: None

Hazardous Polymerization:

May occur _____ Will not occur

Section VII - Spill or Leak Procedures

Steps to be Taken: Vacuum or sweep up excess material to avoid a possible slipping hazard.

Waste Disposal Method: Glass beads may be disposed in a solid waste landfill if permitted by applicable Federal, State, and Local Regulation.

Section VIII - Special Protection Information

Engineering Controls: NIOSH approved dust respirator or dust mask.

Ventilation: Mechanical and local exhaust recommended when generating excessive levels of airborne dust.

Protection Clothing/Equipment:

Gloves: As required per job.

Goggles: Safety glasses or goggles

Other Protection Equipment: None

Section IX - Special Precautions

Handling & Storage Precautions: None

Other Precautions: None

The information and recommendations contained herein are, to the best of Siplast's knowledge and belief, accurate and reliable as of the date issued. Siplast does not warrant or guarantee their accuracy or reliability, and should not be liable for any loss or damage arising out of the use thereof. User should satisfy himself that he has all current data relevant to his particular use.