Stolit 1.0

80130 Stolit 1.0

Technical Data

Pre-Consumer Recycled Content 0%
Post-Consumer Recycled Content 0%
VOC (g/l) 27

Manufacturing Location	Component #	% of Total Product	Extraction Location
Atlanta Facility 6175 Riverside Dr. Atlanta, GA 30331	" A "	41 %	Marble Hill, GA 30148
	"B"	19 %	Berkeley Springs, WV 25411
	"C"	11 %	Atlanta, GA 30331
	"D"	6 %	Sylacauga, AL
Manufacturing Location	Component #	% of Total Product	Extraction Location
Rutland, VT Facility 251 Quality Ln. Rutland Town, VT 05701	" A "	41 %	Florence, VT 05744
	"B"	19 %	Berkeley Springs, WV 25411
	"C"	11 %	Rutland Town, VT 05701
	"D"	6 %	Procter, VT 05765
Manufacturing Location	Component #	% of Total Product	Extraction Location
Glendale, AZ Facility 6504 W. Northern Ave Glendale, AZ 85301	"A"	41 %	Superior, AZ 85273
	"B"	19 %	Mill Creek, OK 74856
	"C"	11 %	Glendale, AZ 85301
	"D"	6 %	Superior, AZ 85273

Sto Corp.

3800 Camp Creek Parkway Building 1400, Suite 120 Atlanta, GA 30331

LEED-80130

Revision: 000 Date Revised:



Attention

Attention This product is intended for use by qualified professional contractors, not consumers, as a component of a larger construction assembly as specified by a qualified design professional, general contractor or builder. It should be installed in accordance with those specifications and Sto's instructions. Sto Corp. disclaims all, and assumes no, liability for on-site inspections, for its products applied imporenty, or by unqualified persons or entities, or as part of an improperly designed or constructed building, for the nonperformance of adjacent building components or assemblies, or for other construction activities beyond Sto's control. Improper use of this product or use as part of an improperly designed or constructed larger assembly or building may result in serious EXPRESS OR IMPLIED EXCEPT FOR EXPLICIT LIMITED WRITTEN WARRANTIES ISSUED TO AND ACCEPTED BY BUILDING OWNERS IN ACCORDANCE WITH STO'S WARRANTY PROGRAMS WHICH ARE SUBJECT TO CHANGE FROM TIME TO TIME. For the fullest, most current information on proper application, clean-up, mixing and other specifications and warranties, cautions and disclaimers, please refer to the Sto Corp. website, <u>www.stocorp.com</u>.

www.stocorp.com

Tel: 404-346-3666 Toll Free: 1-800-221-2397 Fax: 404 346-3119